

SCHOOL LEAD MONITORING RESULTS
 Wheelerville Union Free School

<u>SAMPLE ID</u>	<u>SCHOOL & SAMPLE LOCATION</u>	<u>DATE COLLECTED</u>	<u>LEAD mg/L</u>	<u>Date Analyzed</u> <u>Lead</u>
1608026	E6 - Drinking Fountain	9/18/2016	<0.001	10/24/16
1608062	W42 - Drinking Fountain	9/18/2016	<0.001	10/24/16
1608029	E9 - Drinking Fountain	9/18/2016	0.0014	10/24/16
1608031	E11 - Kindergarten Sin k	9/18/2016	0.002	10/24/16
1608064	W44 - Drinking Fountain	9/18/2016	0.0031	10/24/16
1608025	E5 - 1st Grade Sink	9/18/2016	0.0033	10/24/16
1608046	C26 - Main Prep Sink - Kitchen	9/18/2016	0.004	10/24/16
1608065	W45 - Art Room Sink (2)	9/18/2016	0.0044	10/24/16
1608066	W46 - Speech/Reading Room Sink (1)	9/18/2016	0.0067	10/24/16
1608032	E12 - Kindergarten Bubbler	9/18/2016	0.0069	10/24/16
1608024	E4 - 2nd Grade Sink	9/18/2016	0.0071	10/24/16
1608035	E15 - PreK Bubbler	9/18/2016	0.0072	10/24/16
1608039	C19 -Girls Locker Room Restroom Slnk (Right)	9/18/2016	0.0073	10/24/16
1608063	W43 - Art Room Sink (1)	9/18/2016	0.0073	10/24/16
1608051	C31 - Right Side Scrub Sink - Kitchen	9/18/2016	0.0074	10/24/16
1608048	C28 - Kettle Fill / Rinse Valve - Kitchen	9/18/2016	0.0075	10/24/16
1608050	C30 - Left Side Scrub Sink - Kitchen	9/18/2016	0.0086	10/24/16
1608023	E3 - 3rd Grade Sink	9/18/2016	0.0091	10/24/16
1608021	E1 - 5th Grade Sink	9/18/2016	0.0094	10/24/16
1608030	E10 - Resource Room Sink	9/18/2016	0.0097	10/24/16
1608036	E16 - PreK Sink	9/18/2016	0.0097	10/24/16
1608038	C18 -Girls Locker Room Restroom Sink (Left)	9/18/2016	0.01	10/24/16
1608067	W47 - Speech/Reading Room Sink (2)	9/18/2016	0.011	10/24/16
1608034	E14 - Girl's Restroom Sink	9/18/2016	0.012	10/24/16
1608022	E2 - 4th Grade Sink	9/18/2016	0.016	10/24/16
1608027	E7 - Nurse's restroom sink	9/18/2016	0.017	10/24/16
1608037	C17 - Boys Locker Room Restroom Sink	9/18/2016	0.018	10/24/16
1608041	C21 - Boys Elementary Restroom Sink	9/18/2016	0.019	10/24/16
1608045	C25 - Middle School Boys Restroom Sink (Right)	9/18/2016	0.021	10/24/16
1608053	C33 - Ladies Restroom Room Sink - Receiving Room Area	9/18/2016	0.021	10/24/16

SCHOOL LEAD MONITORING RESULTS
Wheelerville Union Free School

<u>SAMPLE ID</u>	<u>SCHOOL & SAMPLE LOCATION</u>	<u>DATE COLLECTED</u>	<u>LEAD mg/L</u>	<u>Date Analyzed</u> <u>Lead</u>
1608054	C34 - Mens restroom sink - Receiving Room Area	9/18/2016	0.021	10/24/16
1608068	W48 - Superintendent Restroom	9/18/2016	0.024	10/24/16
1608052	C32 - Spray - Wash Valve - Kitchen	9/18/2016	0.025	10/24/16
1608040	C20 - Girls Elementary Restroom Sink	9/18/2016	0.026	10/24/16
1608042	C22 - Middle School Girls Restroom Sink (Right)	9/18/2016	0.026	10/24/16
1608044	C24 - Middle School Boys Restroom Sink (Left)	9/18/2016	0.028	10/24/16
1608028	E8 - Nurse's Exam Room Sink	9/18/2016	0.045	10/24/16
1608043	C23 - Middle School Girls Restroom Sink (Left)	9/18/2016	0.05	10/24/16
1608049	C29 - Hand Wash Sink - Kitchen	9/18/2016	0.055	10/24/16
1608047	C27 - Spray Wash Valve - Kitchen	9/18/2016	0.07	10/24/16
1608061	W41 - Prep Room Sink - Sciene Room	9/18/2016	0.085	10/24/16
1608033	E13 - Boy's Restroom Sink	9/18/2016	0.11	10/24/16
1608056	W36 - Lab Sink - Science room	9/18/2016	0.15	10/24/16
1608055	W35 - Lab Slnk - Science Room	9/18/2016	0.35	10/24/16
1608057	W37 - Lab Sink - Science Room	9/18/2016	0.44	10/24/16
1608058	W38 - Lab Sink - Science Room	9/18/2016	0.44	10/24/16
1608060	W40 - Lab Sink - Science Room	9/18/2016	0.5	10/24/16
1608059	W39 Lab Sink - Science Room	9/18/2016	047	10/24/16